
City of Baltimore Wet Smoke and Dyed	Page 1 of 1	
Sewershed: Gwynns Falls	Company: Savin	Date: 7/29/2009
Test to be performed:  Smoke Dyed Water X Dry ✓ Damp ☐ Wet ☐		Supervisor: <u>JAW</u>
Manhole_ID: S01YY_V01MH	Test ID: <u>D1032-025002</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Manhole	S01YY_V01MH
0			Water Level	
88.5			Dye Test Visible	@ TFA - downspout
92.30000305	12		Tap Factory Active	From 4412 Springdale
92.30000305			Dye Test Visible	@ TFA - toilet
93			Manhole	S01YY_002MH
93			End of Survey	